

Type	L #	Hits	Search Text	DBs	Time Stamp	Comm ents	Error Defin ition	Err ors
1	IS&R	L1 21	((398/19) or (398/12)) .CCLS.	USPAT; US-PGPUB	2003/ 09/16 15:24			0
2	IS&R	L2 1942	((385/16) or (385/17) or (398/48) or (398/50) or (398/55) or (398/56)) .CCLS.	USPAT; US-PGPUB	2003/ 09/16 15:24			0
3	BRS	L3 8584	(verification or verifying or verify or connectivity or testing or tested) near3 (connectivity or connection or connections)	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:24			0
4	BRS	L4 3444	((switch or switching). adj (fabric or fabrics or matrix) or crossconnect or (cross adj connect)).ti,ab.	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:25			0
5	BRS	L5 782	4 and (optic or optical or lightwave).ti,ab.	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:25			0
6	BRS	L6 37	(2 or 5) and 3	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:25			0
7	BRS	L7 90395	(test or testing or monitor or monitoring or supervisory) near2 (signal or signals)	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:26			0
8	BRS	L8 214	(2 or 5) and 7	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:26			0
9	BRS	L9 189	8 not (1 or 6)	USPAT; US-PGPUB; EPO; JPO	2003/ 09/16 15:26			0

08/775 429